

Packing Assembly Parts List (Only Difference)

NOTE : For the parts not mentioned, refer to the Service Manual for PDX-4.100 (Part No. T0110700015).

Model	PDX-4.100 (North American Model)		PDX-4.100M	
Symbol No.	Part No.	Description	Part No.	Description
101	68-08564Z37	MANUAL,OWNER'S(AO)	68-12118Z79	MANUAL,OWNER'S(AO)
106	03E36692S01	WRENCH,4X4.6	47E35195S01	WRENCH,4X4.6

Electrical Parts List (Only Difference)

NOTE : For the parts not mentioned, refer to the Service Manual for PDX-4.100 (Part No. T0110700015).

Model	PDX-4.100		PDX-4.100M	
Symbol No.	Part No.	Description	Part No.	Description
MAIN P.W.Board				
C5003	08E35262S01	CAP,CER. 0.022uF/50V	08E37121S01	CAP,CER. 0.022uF/50V
C5006	08E28771S01	CAP,CER. 0.01uF/50V	08E36567S01	CAP,CER. 0.01uF/50V
C9101	08E28771S01	CAP,CER. 0.01uF/50V	08E36567S01	CAP,CER. 0.01uF/50V
C9701	08E28771S01	CAP,CER. 0.01uF/50V	08E36567S01	CAP,CER. 0.01uF/50V
C9901	08E39186S01	CAP,CER.2200pF/500V	08E39188S01	CAP,CER.2200pF/500V
C9902	08E39186S01	CAP,CER.2200pF/500V	08E39188S01	CAP,CER.2200pF/500V
IC9701	51E36569S01	IC,uPC494GS-E1-A	51E39140S01	IC,uPC494GS-E1-A
Q4501	48E22555S01	TR,DTC144EK	48E36573S01	TR,DTC144EK
Q4502	48E22555S01	TR,DTC144EK	48E36573S01	TR,DTC144EK
Q4514	48E22902S01	TR,2SC2412K	48E36571S01	TR,2SC2412K
Q4551	48E22555S01	TR,DTC144EK	48E36573S01	TR,DTC144EK
Q4552	48E22555S01	TR,DTC144EK	48E36573S01	TR,DTC144EK
Q9101	48E22902S01	TR,2SC2412K	48E36571S01	TR,2SC2412K
Q9501	48E22555S01	TR,DTC144EK	48E36573S01	TR,DTC144EK
Q9502	48E22902S01	TR,2SC2412K	48E36571S01	TR,2SC2412K
Q9503	48E22902S01	TR,2SC2412K	48E36571S01	TR,2SC2412K
Q9701	48E22092S01	TR,DTA124EKA	48E36597S01	TR,DTA124EKA
R3050	06E31148S01	RES,CF. 100-1/16W	06E36616S01	RES,CF. 100-1/16W
R4107	06E33314S01	RES,CEMENT 0.01-5W	06E36600S01	RES,CEMENT 0.01-5W
R4109	06E33314S01	RES,CEMENT 0.01-5W	06E36600S01	RES,CEMENT 0.01-5W
R4111	06E33314S01	RES,CEMENT 0.01-5W	06E36600S01	RES,CEMENT 0.01-5W
R4113	06E33314S01	RES,CEMENT 0.01-5W	06E36600S01	RES,CEMENT 0.01-5W
R9704	06E31153S01	RES,CF. 2.2K-1/16W	06E36585S01	RES,CF. 2.2K-1/16W
T9901	25E40378S01	TRANS,POWER 3T/8T	25E40811S01	TRANS,POWER PMAL603A
SUB P.W.Board				
R1301	06E31148S01	RES,CF. 100-1/16W	06E36616S01	RES,CF. 100-1/16W
R1306	06E31148S01	RES,CF. 100-1/16W	06E36616S01	RES,CF. 100-1/16W
Miscellaneous				
F001	65E25308S01	FUSE,AUTO 30A	65E38096S01	FUSE,AUTO 30A
F002	65E25308S01	FUSE,AUTO 30A	65E38096S01	FUSE,AUTO 30A


Cabinet Assembly Parts List (Only Difference)

NOTE : For the parts not mentioned, refer to the Service Manual for PDX-4.100 (Part No. T0110700015).

Model	PDX-4.100			PDX-4.100M		
Symbol No.	Index	Part No.	Description	Index	Part No.	Description
11		33E39157S01	PLATE,NAME		33E40801S01	PLATE,NAME
12		33E39669S01	PLATE,NAME-F		33E40802S01	PLATE,NAME(F)
30		16E39454S01	CAP,TOP		16E40803S01	CAP,TOP
31		03E39505S01	SCR,M3X10(F)(BLK)		03E40804S01	SCR,M3X10(F)(BLK COAT)
32		03E39507S01	SCR,M2.6X8(B)(BLK)		03E40805S01	SCR,M2.6X8(B)(SUS)
33		03E38698S01	SCR,M3X8(P)(BLK)		03E40808S01	SCR,M3X8(P)(SUS)
40		03E39676S01	SCR,M2.6X7(B)(BLK)		03E40809S01	SCR,M2.6X7(B)(SUS)
47		_____	_____		03E40807S01	SCR,M3X10(P)(SUS)
48		_____	_____		03E40806S01	SCR,M3X6(B)(SUS)

Exploded View (Cabinet)

PDX-4.100M



TO CONTENTS