KENWOOD

SERVICE MANUAL

MONITOR WITH RECEIVER

DMX4710S, DMX40S
DMX5023S, DMX400S

SERVICE POLICY

No service parts available except accessory.



Bluetooth
Made for iPhone
Works with Apple CarPlay
Android Auto

DC Cable
E3A-1026-00(DMX4710S)
E3A-1027-00(DMX5023S)



Extension Parking Cable
E3A-0344-00

Remover
D1C-0006-00

Trim Plate
B0H-0068-00



GPS Antenna Assy
T9A-0147-00



Microphone
T9B-0092-00

COPYRIGHT © 2024 JVCKENWOOD Corporation

WA515
2024/10

【Service Parts Configuration Table】

	DMX4710S(K)	DMX40S(K)	DMX400S(K)WM	DMX5023S(M)
E3A-1026-00	O	O	O	
E3A-1027-00				O
E3A-0344-00	O	O	O	O
D1C-0006-00	O	O	O	O
B0H-0068-00	O	O	O	O
T9A-0147-00	O	O	O	O
T9B-0092-00	O	O	O	

【Revision History】

Date	Revision
2024/9/20	Additional model DMX400S (K type WM)

KENWOOD

JVCKENWOOD Corporation
Mobility & Telematics Services

(WA515)

Printed in Japan